



Colour Reference Chart

GKE Clean-Record®
Cleaning Process Monitoring Indicators for
ultrasonic cleaning baths

Indicator has been fully washed off



Indicator has been partially washed off/ Information about ultrasonic cleaning efficacy



Indicator has NOT been washed off



yellow

green

blue

red



+EGKE720009EDM0/SS12995F